DMR Copy of Record

Permit Permit #:

MAR054014

Thebearge

Permittee: **Boston Concrete Corporation**

Major: No Permittee Address:

706 Broadway Street Lowell, MA 01854

Facility Location:

BOSTON CONCRETE CORPORATION

Facility:

706 BROADWAY STREET LOWELL, MA 01854

Permitted Feature:

001 External Outfall

Discharge:

001-E2

Concrete and Gypsum Product Manufacturers

Report Dates & Status

Monitoring Period: From 07/01/18 to 09/30/18 DMR Due Date: 11/28/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Dave Title: **Operations Manager** Telephone:

978-490-9810

No Data Indicator (NODI)

Form NODI:

Last Name:

| | 1 0111111 | 001. | | | | | | | | | | | | | | | | | |
|-----------|-----------|-------------------------|--|---|--|-------------|---------------------|---------|-------------|--------------------------|---------------|---------|-----------------------|-------------|--|-----------|--|-------------------|-----------|
| Parameter | | Parameter | Monitoring Location Season # Param. NODI | | | | Quantity or Loading | | | Quality or Concentration | | | | | # of Ex. Frequency of Analysis Sample Type | | | | |
| | Code | Name | | | | | Qualifier 1 | Value 1 | Qualifier 2 | Value 2 Unit | s Qualifier 1 | Value 1 | 1 Qualifier 2 Value 2 | Qualifier 3 | Value 3 | Units | | | |
| 2 | | Solids, total suspended | 1 - Effluent Gross | 0 | | Sample | | | | | | | | = | 460 | 19 - mg/L | | 01/90 - Quarterly | GR - GRAB |
| | X 00530 S | | | | | Permit Req. | | | | | | | | <= | 100 MAXIMUM | 19 - mg/L | | 01/90 - Quarterly | GR - GRAB |
| | | | | | | Value NODI | | | | | | | | | | | | | |
| 2 | X 01045 l | Iron, total [as Fe] | 1 - Effluent Gross | 0 | | Sample | | | | | | | | = | 15 | 19 - mg/L | | 01/90 - Quarterly | GR - GRAB |
| | | | | | | Permit Req. | | | | | | | | <= | 1 MAXIMUM | 19 - mg/L | | 01/90 - Quarterly | GR - GRAB |
| | | | | | | Value NODI | | | | | | | | | | | | | |

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

| | Parameter | Monitoring Location | Field | Туре | Description | Acknowledge | |
|-------|-------------------------|---------------------|---|------|--|--------------|--|
| Code | Name | Monitoring Location | rieu | | Description | Ackilowiedge | |
| 01045 | Iron, total [as Fe] | 1 - Effluent Gross | Quality or Concentration Sample Value 3 | Soft | The provided sample value is outside the permit limit. (Error Code: 1) | Yes | |
| 00530 | Solids, total suspended | 1 - Effluent Gross | Quality or Concentration Sample Value 3 | Soft | The provided sample value is outside the permit limit. (Error Code: 1) | Yes | |

Comments

Attachments

| Name | Туре | Size |
|---------------------------------------|------|--------|
| Sept18StormwaterQuartelyBenchmark.pdf | pdf | 387425 |

Report Last Saved By

Boston Concrete Corporation

DTHEBEARGE User: Name: David Thebearge

E-Mail: dthebearge@bostonconcrete.com Date/Time: 2018-09-19 11:16 (Time Zone: -04:00)

Report Last Signed By

User: DTHEBEARGE David Thebearge Name:

E-Mail: dthebearge@bostonconcrete.com Date/Time: 2018-09-19 11:17 (Time Zone: -04:00)